

Electrical / Environmental

HM37

High Current Low Loss Ferrite Cube Inductors

• Operating Temperature Range

-40°C to +130°C







Schematic




Specifications @ 25°C							
	—— Inductance —— 100 kHz, 0.1 V						
Part	@ 0 A	@ I _{sat}	Heating Current ⁽¹⁾ (Adc)	I _{sat} ⁽²⁾	DCR		
Number	$nH \pm 10\%$	nH Typ.	(Adc)	(Adc)	$(m\Omega) \pm 5\%$		
HM37-1007R17LF	170	158	42	58	0.37		
HM37-1007R19LF	190	180	42	50	0.37		
HM37-1609R32LF	320	260	48	50	0.47		


Notes: (1) The heating current is the DC current which causes the component temperature to increase by approximately 50°C. This current is determined by soldering the component on a typical application PCB, and then applying the current to the device for 30 minutes.

(2) The saturation current (I_{sat}) is the approximate current at which inductance will be decreased by 20% from its initial (zero DC) value.


Top View

Outline Dimensions (mm)





Recommended Solder Pad Layout



Case Size	Α	В	С	D
1007	10.0	7.0	9.5	8.5
1609	15.9	8.9	9.2	14.6

Packaging

Standard: Vacuum Tray

Case Size	Capacity Per Carton		
	(Units)		
1007	800		
1609	660		



Electrical Characteristics @ 25°C

